Date: User: Thursday, 21/08/2008 5:11:54 PM

Julie Lecocq

## **Process Sheet**

Customer

: CU-DAR001 Dart Helicopters Services

Job Number **Estimate Number** 

: 41550 : 11493

P O Number

: 21/08/2008 This Issue Prsht Rev.

: NC

: // : 37761 Type

S.O. No. :

: SMALL /MED FAB

**Drawing Number** 

**Part Number** 

**Drawing Name** 

**Project Number Drawing Revision** 

Material

**Due Date** : 29/08/2008

: LANYARD ASSEMBLY

: D26906

: N/A

: B2

: D2690 REV. B2

Qtv:

Each

Checked & Approved By

Comment

First Issue

Written By

**Previous Run** 

Reformat; Incorporated D2690-X KJ/

RF

**Additional Product** 

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

1.0

CBL460

Loop Sleeve

Comment: Qty.: 2.0000 Each(s)/Unit 24.0000 Each(s) Total:

Loop Sleeve

Qty Part Number Description Batch

2 CBL-460 Loop Sleeve

M109062

2.0

CBL1240

Comment: Qty.: 12.0000 f(s) 1.0000 f(s)/Unit Total:

Cable

Qty

Part Number Description Batch

D2690-6 + 2.5" CBL-1240 Cable / SMALL FAB

3.0



Comment: SMALL & MEDIUM FAB RESOURCE 1

Assemble as per Dwg D2690

Identify as D2690-6

4.0 QC5 INSPECT WORK TO

Comment: INSPECT WORK TO CURRENT STEP

5.0

PACKAGING RESOURCE #1

Comment: PACKAGING RESOURCE #1

Identify and Stock

Location:

Dart Ae	rospace	Ltd										
W/O:			<u> </u>	W	ORK ORDER CH	NGES						
DATE STEP			PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto	
			AR #: Fault Category:			NCR: Yes No DQA: Date:						
				Dispositi	QA: N/C Closed: Date:							
NCR:				WORK ORE	DER NON-CONFO	RMANCE	(NCR	)				
DATE	STEP	<b>Description</b> Section		Corrective Action		Section B		Verific	cation	Approval	Approva	
DATE				Initial Chief Eng	Action Descrip	tion	Sign & Date		on C	Chief Eng	QC Inspecto	
			· 									
							:					
							į					
	1	,								:		

NOTE: Date & initial all entries

Date: User: Thursday, 21/08/2008 5:11:54 PM

Julie Lecocq

**Process Sheet** 

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LANYARD ASSEMBLY

Job Number: 41550

Part Number: D26906

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

6.0

QC21

FINAL INSPECTION/W/O RELEASE



MF 08-09-23

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



Dart Ae	rospace	Ltd										
W/O:				WO	RK ORDER CH	ANGES						
DATE STEP			PROCEDURE CHANGE				Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto		
}												
Part No:P		AR #: Fault Category:			NCR: Yes No DQA: Date:							
Resolution:				Disposition:			QA: N/C Closed: Date:					
NCR:			1	WORK ORDE	R NON-CONFO	RMAN	CE (NCR	)				
DATE	STEP	<b>Description</b> Section	of NC	Corrective Action		Section B		Verification	1 Approval	Approva		
				Initial Chief Eng	Action Descri Chief Eng	tion	Sign & Date	Section C	Chief Eng	QC Inspecto		
								1				
										*		
		.										
					• • •							
		1										

NOTE: Date & initial all entries






BZ

	DESIGN DR		DRAWN BY	DART AEROSPACE LTD						
1	V	100	1 KE	VICTORIA INTERNATIONAL AIRPORT, CANADA						
	CHECKED.		APPROVED	DRAWING NO. REV.	8					
	ĵ.	YI MY	BW	D2690 SHEET 1 OF	•					
	V	V 100 + 500			1					
	DATE			TITLE SCA	LE					
	97.1	10.02		LANYARD ASSEMBLY N	TS					
	Α		97.07.03	NEW ISSUE						
	В		97.10.02	REVISED NOTE FOR ADDITIONAL LENGTH						
	BI	dece	01 08.20	ADD NOTE TO REMOVE 2.25" OF SLEEVE						

ADDED TOLERANCE





TX 04.06.24

## D2690-X

## X = LENGTH IN INCHES

CUT CABLE 2.50\* INCHES LONGER THAN 'X' LENGTH. NOTE:

FOLD ENDS TIGHT TO 'X' LENGTH AND CRIMP WITH

SLEEVE AT END OF LOOSE END OF CABLE WITH

CBL-705 CRIMPING TOOL.

\*ADDITIONAL LENGTH MAY BE NECESSARY IN SOME APPLICATIONS. CUT AS REQUIRED.

SHOP COPY RETURN TO ENGINEERING UNCONTROLLED COPY

IN SOME CASES, END HAS TO BE CRIMPED AFTERWITHOUT NOTICE ASSEMBLY WITH ATTACHING DARKS NOTE:

WORK ORDER ASSEMBLY WITH ATTACHING PARTS.

DEO's